


ENVIRONMENTAL, CE 2020 Annual Sustainability Report



Kallpa Generación S.A. (Kallpa, Las Flores, Cerro del Aguila)




*Natural Gas includes both Combined Cycle CC and Open Cycle OC operations.




Reduction in generation in 2020 due to lower demand of electricity as result of COVID-19 pandemic.


1. Safety Performance




Generation and Distribution Safety Performance Employee and Contractors

2. Environmental Stewardship





Internal Energy Consumption (MWh)




Industrial Solid Waste (Tons) Non-Hazardous Waste (tons) Hazardous Waste (tons)

Non-hazardous wastes higher than target due to major maintenance performed in units TG1 and TG3 of Kallpa plant, replacement of stack thermal isolation of Las Flores plant and air filters in all units.

Carbon Intensity Benchmark


(Tons CO₂/MWh)



3. Social Responsibility and Community Engagement




Social Investment (US\$)




Social Investments lower than target due to restrictions imposed by governments in response to COVID-19 sanitary crisis. A total of US\$ 353K of existing and approved additional funds were invested to support COVID-19 vulnerable communities.

Number of Individuals Benefited
(#)




4. Operational Excellence

Operational Performance




36

5. Workforce




Workforce (#)

Executives (#)







Training Hours (#)

